


E80

Experimental
Engineering

$$SSE = \sum_{i=1}^N e_i^2 = \sum_{i=1}^N \left[y_i - (\hat{\beta}_0 + \hat{\beta}_1 x_i) \right]^2$$

SIGNIFICANCE LEVEL FOR TWO-TAILED TEST

df	.20	.10	.05	.02	.01	.001
1	3.078	6.314	12.706	31.821	63.657	636.619
2	1.886	2.920	4.303	6.965	9.925	31.598
3	1.638	2.353	3.182	4.541	5.841	12.941
4	1.533	2.132	2.776	3.747	4.604	8.610



Lecture 2E – Linear Regression

1

E80

Experimental
Engineering

Overview of Linear Regression


- Take data.
- Assume linear.
- Perform regression.
- Report slope and intercept.
- Plot data, line, uncertainties.

$$\hat{\beta}_1 = 0.183 \pm 0.067 (80\% \text{ conf.})$$

$$\hat{\beta}_0 = 2.238 \pm 0.418 (80\% \text{ conf.})$$

Partial list of techniques:

- Least Squares
- Least Absolute Deviation (LAD)
- Median-Median
- Least Median of Squares (LMS)




2

E80

Experimental
Engineering

Overview of Linear Regression

- Take data.
- Assume linear.
- Perform regression.
- Report slope and intercept.
- Plot data, line, uncertainties.



$$\hat{\beta}_1 = 0.183 \pm 0.067 (80\% \text{ conf.})$$

$$\hat{\beta}_0 = 2.238 \pm 0.418 (80\% \text{ conf.})$$

Partial list of techniques:

- **Least Squares**
- Least Absolute Deviation (LAD)
- Median-Median
- Least Median of Squares (LMS)

3

E80

Experimental
Engineering

Measurements and Residuals

The set of measurements

$$\{(x_1, y_1), (x_2, y_2), \dots, (x_N, y_N)\}$$

$$y_i = \beta_0 + \beta_1 x_i + \varepsilon_i$$

Can we calculate the error?

$$\varepsilon_i = y_i - (\beta_0 + \beta_1 x_i)$$

The set of errors $\{\varepsilon_1, \varepsilon_2, \dots, \varepsilon_N\}$

Calculate the residual

$$e_i = y_i - \hat{y}_i = y_i - (\hat{\beta}_0 + \hat{\beta}_1 x_i)$$

The set of residuals

$$\{e_1, e_2, \dots, e_N\}$$

The Sum of Squared rEsiduals, SSE

$$\sum_{i=1}^N e_i^2 = \sum_{i=1}^N (y_i - \hat{y}_i)^2 = \sum_{i=1}^N \left[y_i - (\hat{\beta}_0 + \hat{\beta}_1 x_i) \right]^2$$

4

E80

Experimental
Engineering

Best-Fit Slope & Intercept

$$\hat{\beta}_1 = \frac{\sum_{i=1}^N (x_i - \bar{x})(y_i - \bar{y})}{\sum_{i=1}^N (x_i - \bar{x})^2}$$

$$\hat{\beta}_0 = \bar{y} - \hat{\beta}_1 \bar{x}$$

Root Mean Squared rEsidual (*RMSE*)

$$RMSE = S_e = \sqrt{\frac{SSE}{N-2}} = \sqrt{\frac{\sum_{i=1}^N e_i^2}{N-2}}$$

Lose two degrees of freedom by calculating $\hat{\beta}_0, \hat{\beta}_1$

5

E80

Experimental
Engineering

Standard Errors & C.I.'s

Standard Errors

$$S_{\beta_0} = S_e \sqrt{\frac{1}{N} + \frac{\bar{x}^2}{\sum_{i=1}^N (x_i - \bar{x})^2}}$$

$$S_{\beta_1} = S_e \sqrt{\frac{1}{\sum_{i=1}^N (x_i - \bar{x})^2}}$$

Confidence Intervals

$$\lambda_{\beta_0} = t S_{\beta_0}$$


Remember: $df = N - 2$

$$\lambda_{\beta_1} = t S_{\beta_1}$$

6

E80Experimental
Engineering


Histograms to Lines



7

E80Experimental
Engineering


Histograms to Lines



8

E80Experimental
Engineering


Histograms to Lines



9

E80Experimental
Engineering

Histograms to Lines




10

E80

Experimental
Engineering

Histograms to Lines




11

E80

Experimental
Engineering

Histograms to Lines




12

E80

Experimental
Engineering

Histograms to Lines




13

E80

Experimental
Engineering

Histograms to Lines




14

E80

Experimental Engineering

Histograms to Lines




15

E80

Experimental Engineering

Histograms to Lines




16

E80

Experimental Engineering

Histograms to Lines




17

E80

Experimental Engineering

Histograms to Lines




18

E80

Experimental Engineering

Histograms to Lines




19

E80

Experimental Engineering

Histograms to Lines




20

E80

Experimental Engineering

Histograms to Lines




21

E80

Experimental Engineering


Histograms to Lines



22

E80Experimental
Engineering


Histograms to Lines



23

E80Experimental
Engineering

Histograms to Lines




24

E80

Experimental Engineering

Histograms to Lines




25

E80

Experimental Engineering

Histograms to Lines




26

E80

Experimental Engineering

Histograms to Lines




27

E80

Experimental Engineering

Histograms to Lines




28

E80

Experimental Engineering

Histograms to Lines




29

E80

Experimental Engineering

Histograms to Lines




30

E80

Experimental Engineering

Histograms to Lines




31

E80

Experimental Engineering

Histograms to Lines



32

E80

Experimental
Engineering

Confidence Bounds

Confidence bound on line or mean value \hat{y} at x (functional bound)

$$S_{\hat{y}} = S_e \sqrt{\frac{1}{N} + \frac{(x - \bar{x})^2}{\sum_{i=1}^N (x_i - \bar{x})^2}} \quad \lambda_{\hat{y}} = tS_{\hat{y}} \quad \begin{aligned} y_{ucb\hat{y}} &= \hat{\beta}_0 + \hat{\beta}_1 x + \lambda_{\hat{y}} \\ y_{lcb\hat{y}} &= \hat{\beta}_0 + \hat{\beta}_1 x - \lambda_{\hat{y}} \end{aligned}$$

Confidence bound on data (observational bound)

$$S_y = S_e \sqrt{1 + \frac{1}{N} + \frac{(x - \bar{x})^2}{\sum_{i=1}^N (x_i - \bar{x})^2}} \quad \lambda_y = tS_y \quad \begin{aligned} y_{ucby} &= \hat{\beta}_0 + \hat{\beta}_1 x + \lambda_y \\ y_{lcb_y} &= \hat{\beta}_0 + \hat{\beta}_1 x - \lambda_y \end{aligned}$$

33

E80

Experimental
Engineering

Example

x_i (Hours of Sleep)	y_i (GPA)
7.5	3.70
4.0	3.10
6.0	3.32
5.0	2.98
8.0	3.68

$$\hat{\beta}_1 = \frac{\sum_{i=1}^N (x_i - \bar{x})(y_i - \bar{y})}{\sum_{i=1}^N (x_i - \bar{x})^2} = 0.183 \quad S_{\beta_1} = S_e \sqrt{\frac{1}{\sum_{i=1}^N (x_i - \bar{x})^2}} = 0.0407$$

$$\hat{\beta}_0 = \bar{y} - \hat{\beta}_1 \bar{x} = 2.238 \quad S_{\beta_0} = S_e \sqrt{\frac{1}{N} + \frac{\bar{x}^2}{\sum_{i=1}^N (x_i - \bar{x})^2}} = 0.255$$

$$S_e = \sqrt{\frac{\sum_{i=1}^N e_i^2}{N-2}} = 0.136 \quad t(df = 3, 80\% \text{ conf.}) = 1.638$$

34

E80


Experimental Engineering

Example (cont.)

	x_i (Hours of Sleep)	y_i (GPA)
	7.5	3.70
	4.0	3.10
	6.0	3.32
	5.0	2.98
	8.0	3.68
mean	6.1	3.36

$$\hat{\beta}_1 = 0.183 \pm 0.067 (80\% \text{ conf.})$$

$$\hat{\beta}_0 = 2.238 \pm 0.418 (80\% \text{ conf.})$$




35

E80

Experimental Engineering

Example (cont.)



$$y = 2.238 + 0.183 \cdot 7 = 3.52$$

$$S_y = S_e \sqrt{1 + \frac{1}{N} + \frac{(x - \bar{x})^2}{\sum_{i=1}^N (x_i - \bar{x})^2}} = 0.154$$

$$\lambda_y = t S_y = 0.254$$

$$y(7) = 3.52 \pm 0.254 = [3.27 \quad 3.77]$$


36

E80

Experimental Engineering

What Does It Mean?

$$\lambda_{\dot{y}} = tS_{\dot{y}}$$




$$S_{\dot{y}} = S_e \sqrt{\frac{1}{N} + \frac{(x - \bar{x})^2}{\sum_{i=1}^N (x_i - \bar{x})^2}}$$

37

E8

Experim Engineering



38

E80

Experimental
Engineering

Takaways

1. For a line, make at least four measurements.
2. DO NOT calculate these things by hand. Use a software package.
3. Report your results with the confidence interval and the confidence level, e.g., $\hat{\beta}_1 = 0.183 \pm 0.067(80\% \text{ conf.})$ $\hat{\beta}_0 = 2.238 \pm 0.418(80\% \text{ conf.})$
4. Plot data points, best-fit curve, function confidence bound, data confidence bound.